
JIG FIXTURE FOR 15mm GLASS BGA




ACCESSORIES INCLUDED			
QTY	DESCRIPTION		
6	PRESSURE WEIGHTS 12.7 x 12.7 x 19.0mm		
1	Vacuum Pick up Tool		




NOTES: (UNLESS OTHERWISE SPECIFIED).

1. DIMENSIONS: mm (INCH).

APPROVA	ALS	DATE	TopLine°				
DRAWN	T.Au	9/26/2021			·		
ENG	M. Hart	9/26/2021	TITLE JIG FIXTURE				
MFG			15mm GLASS BGA				
QA			SCALE	SIZE DRAWING NO. REV		REV	
CUST			3:2	Α	A 999099 A		Α
REVISED			DO NOT SCALE DRAWING SHEET 1 OF 4				




AFTER ASSEMBLY GLASS COMPONENTS ARE GLUED TO STAND OFF PINS



<u>TopLine</u> °						
JIG FIXTURE 15mm GLASS BGA						
SCALE	SIZE	DRAWING NO.	REV			
2:1	Α	999099		Α		
DO NOT S	SHEET	3 OF 4				

ASSEMBLY INSTRUCTIONS

- 1.Place Jig Fixture 999099 on top of BGA Standoff Board.
- 2.Dispense small amount of Cyanoacrylate Glue Gel on tips of the stand off pins.
- 3. Gently place Glass Component on the stand off pins using vacuum pick up tool
- 4. Place 5 to 25 grams weight on top of each glass component to apply pressure to glass during curing.
- 5. Remove the weights and Jig Fixture after the glue cures.
- 6. Proceed to test underfill.



<u>TopLine</u> °						
JIG FIXTURE 15mm GLASS BGA						
SCALE	SIZE	DRAWING NO.	REV			
4:1	Α	999099		Α		
DO NOT SCALE DRAWING SHEET 4				4 OF 4		