

Flux Designation System

RO L 1



RO = Rosin
RE = Resin
OR = Organic
IN = Inorganic

L = Low
M = Medium
H = High

0 = Without Halide
1 = With Halides

Percentage Content

L1 = < 0.5% Halide
M1 = 0.5% ~ 2.0% Halide
H1 = > 2.0% Halide

Notes:

No-Clean Fluxes can be “**RO**” or “**RE**” (with or without halides)

“**OR**” fluxes must be without halide (example: ORL0)

“**IN**” fluxes are used by plumbers (normally not used in electronics)